
## ADJUSTMENT ON GAME PC BOARD (ENFORCE G25 00526A)

H-CONNECTOR

	OUTL C.O.		
1	GND	5	GND
2	GND	6	
3	GND	7	+57
4	GND	8	+57

9 10 11 12	+57			
10	POST			
	+57			
12	+57			



G-CONNECTOR

SOLDER SIDE	COAA	COMPONENTS SIDE				
GND	٨	1	GND			
GND	В	2	GND			
+5Y	C	3	+5V			
+5V	D	4	+5V			
-5V	E	5	-5V			
+13V	F	6	+12V			
POST	Н	7	POST			
	J	8	ACCEL SW			
VOLUME 2	К	9	VOLUME 1			
VOLUME 3	L	10	GND			
U-D O	И	11	R-L O			
U-D 1	N	12	R-L 1			
U-D 2	P	13	R-1. 2			
START SW	R	14				
GATLING GUN BUTTON	S	15				
LASER GUN BUTTON	T	.16	SERVICE SW			
COIN SW B	U	17	COIN SW A			
COIN METER B	٧	18	COIN METER A			
COIN LOCKOUT B	W	19	COIN LOCKOUT A			
•	X	20				
VIDEO G	Y	21	VIDEO R			
VIDEO SYNC	Z	22	VIDEO BL			
SOUND (+)	a	23	VIDEO GND			
SOUND (-)	b	24	SCOPE R			
SCOPE GND'	С	25	SCOPE L			
HEAD PHONE (-)	d	26	HEAD PHONE (+)			
GND	е	27	GND			
GND	f	28	GND			

NOTE) SHOULD BE MADE WHEN THE POWER IS OFF.

DIP SW-A:

(\*) : FACTORY SETTINGS

SETTINGS	POSITIONS	1	2	3	4	5	6	7	8
TEST HODE	* NORMAL GAME			OFF					٠
TEST NODE	TEST NODE		·	ON					
ATTRACT COUNTS	+ WITH				OFF				
ATTRACT SOUNDS	WITHOUT				ON				
	+ 1 COIN - 1 PLAY	OFF				OFF	OFF		
PLAY PRICING	2 COINS - 1 PLAY					ON.	<u> </u>		
COIN SLOT-A	3 COINS - 1 PLAY					OFF	ON		
	4 COINS - 1 PLAY					ON	<u> </u>		
PLAY PRICING COIN SLOT-B	* 1 COIN - 2 PLAYS	-						OFF	OFF
	1 COIN - 3 PLAYS							ON	
	1 COIN - 4 PLAYS							OFF	ON
	1 COIN - 6 PLAYS							ON	

DIP SW-B

SETTINGS		POSITIONS	1 .	2	3	4	5	6	7	8
DIFFICULTY LEVEL EASY (A)→HARD (D)		RANK B	OFF	OFF						
		RANK A	ON		OFF					
		RANK C	OFF	ON						
		RANK D	ON						01	FF
	*	NORMAL			Ū	• •	OFF	OFF	0,	•
a b cri rettou	3-D						ON			
3-D SELECTION	NO	RMAL / 3-D					OFF	ON		:.
		SELECTION					ON			

